

Edit all

Copy link

×

Found cracked on scalping screen cover, need to be replaced,

TA Event *

SPCo 2022 SP

Area *

PE

Notification Groups *

Azizi, Deni F

Ahmad, Tariq T

Al-Anazi, Homoud M

Al-Anezi, Thamer M

Manikandan, Subramaniyan [c]

Equipment Tag # *

43S86 Scalping Screen

System Name *

Extruder Package

Brief Description *

Found cracked on scalping screen cover, need to be replaced, the spare cover of scalping screen is available.

Operations Approval

Yes

Meets TA Criteria

No

DWR/CMF

CMF

Estimated

Yes

TA Approval

No

DWR Status

Approved

Scheduled In Worklist

Yes

Execution Status

Complete (P6)

Estimated Cost

43	SPCo 2022 SP	PE	43E55 Heavies KO Condenser CWS &...	43E55	Cooling Water	↘
44	SPCo 2022 SP	PE	42E16 Hexene Cooler Side Draw CWS...	42E16 Hexene Cooler Side Draw	Cooling Water	↘
45	SPCo 2022 SP	PE	U42 CWS & CWR Battery Limit valves...	U42 CWS & CWR Battery Limit	COOLING WATER	↘
55	SPCo 2022 SP	PE	42" CWS & CWR valves in battery lim...	43 CWS & CWR Battery	COOLING WATER	↘
57	SPCo 2022 SP	PE	3/4" bypass of Main Ethylene isolatio...	U42 C2 bypass valve B.L	OSBL	↘
61	SPCo 2022 SP	PE	Replace & re-weld of IPL check valve	SPCO-P-2692 / NRV-42-612-42379	OLEFIN FREE SYS	↘
62	SPCo 2022 SP	PE	Replace damaged IPL check valve & r...	SPCO-SP-2693 / NRV-42-612-42389	OLEFIN FREE SYS	↘
63	SPCo 2022 SP	PE	Replace the damaged IPL check valve...	SPCO-SP-2708 / NRV-43-612-43379	OLEFIN FREE SYS	↘
64	SPCo 2022 SP	PE	Replace the damaged IPL check valve...	SPCO-SP-2709 / NRV-43-612-43389	OLEFIN FREE SYS	↘
66	SPCo 2022 SP	PP	Both CWS and R Passing Valves Need...	CW SYSTEM OSBL CWS and R 36" Valves	CW SYSTEM	↘
67	SPCo 2022 SP	PP	CW System- PNRU Compressor Lube ...	CW SYSTEM- PNRU Compressor LO 44PCV06137 U/S Valve	CW SYSTEM	↘
68	SPCo 2022 SP	PP	HYDROGEN SYSTEM- Broken Bleeder...	HYDROGEN SYSTEM	HYDROGEN SYSTEM	↘
69	SPCo 2022 SP	PP	REACTOR FEED SYSTEM- 44D11 Outl...	REACTOR FEED SYSTEM- 44D11 Outlet Valve and 44P11AB Suction and Discharge Passing Valves	REACTOR FEED TANK	↘

[Skip to main content](#)

70	SPCo 2022 SP	PP	TEAL SYSTEM- 44PRD02122 Passing ...	TEAL SYSTEM- 44PRD02122 Passing Upstream Bleeders Replacement	TEAL SYSTEM	1
73	SPCo 2022 SP	PE	3/4" U/S of steam trap is broken and ...	43 HP Steam valves	HP STEAM & CONDENSATE	1
75	SPCo 2022 SP	PE	End-to-end Functional test is require...	South Plot	INRU & Reactor pump seal	1

[Skip to main content](#)

[Skip to main content](#)

[Skip to main content](#)

[Skip to main content](#)

